

HANDOVER



Sample boat "Nordwind"

DEMO-BOAT-01

OWNER

Demo Render

RENTER

Demo Sample Customer

MEASUREMENTS

412 h

Operating hours

Fuel level



90 %

RENTAL PERIOD

31.08.2026

19:02 h

Requested by: Demo Render

2 photos · 2 damages


NOTES

This is a sample protocol. It was created automatically so you can see right away what a finished protocol looks like — you can delete it at any time. Handover in calm weather, tank full. Briefing on engine and radio completed.

INVENTORY CHECKLIST

#	DESIGNATION	STATUS
6	life jackets	✓ Present
1	anchor with line	✓ Present
1	boat hook	✓ Present
2	mooring lines	✗ Missing
1	first aid kit	✓ Present

PHOTOS AT HANDOVER (2)



Object photo 1 · 31.08.2026 19:02 · 2 damages



Object photo 2 · 31.08.2026 19:02

DAMAGES

1 Damage

Object photo 1

Scratch in the port side hull, approx. 20 cm, above the waterline — gelcoat superficially damaged, no water ingress.



2 Damage

Object photo 1

Chafe mark on the stern next to the pushpit, approx. 10 cm.



SIGNATURE

Sample — not signed

A real protocol is signed here on the device.

Demo Sample Customer · *Renter*

31.08.2026 19:02 h

By signing I confirm the handover of the rental asset in the condition described in this protocol.



Scan QR code for digital protocol

Scan the QR code to view the protocol on your device.

<https://www.rentalhandover.com/p/4c4f09d3-052a-455e-94e1-8051d0...> 85

Link valid until: 29.11.2026



Created with RentalHandover SaaS · Demo Render · 31.08.2021