

HANDOVER



Sample equipment "Cordless drill 18 V"

DEMO-MACHINE-01

OWNER

Demo Render

RENTER

Demo Sample Customer

MEASUREMENTS

—

RENTAL PERIOD

31.08.2026

18:36 h

Requested by: **Demo Render**

2 photos · 2 damages


NOTES

This is a sample protocol. It was created automatically so you can see right away what a finished protocol looks like — you can delete it at any time. Both batteries handed over charged, function checked. Briefing on the torque setting completed.

INVENTORY CHECKLIST

#	DESIGNATION	STATUS
1	charger	✓ Present
2	batteries 18 V	✓ Present
4	drill bits	✓ Present
6	screwdriver bits	✗ Missing
1	side handle	✓ Present
1	case	✓ Present

PHOTOS AT HANDOVER (2)



Object photo 1 · 31.08.2026 18:36 · 2 damages



Object photo 2 · 31.08.2026 18:36

DAMAGES

1 Damage

Object photo 1

Scratch on the gearbox housing, approx. 4 cm, function unaffected.



2 Damage

Object photo 1

Chafe mark on the battery foot, the latch still engages properly.



SIGNATURE

Sample — not signed

A real protocol is signed here on the device.

Demo Sample Customer · *Renter*

31.08.2026 18:36 h

By signing I confirm the handover of the rental asset in the condition described in this protocol.



Scan QR code for digital protocol

Scan the QR code to view the protocol on your device.

<https://www.rentalhandover.com/p/edeef083-4abd-4a4c-963c-f622fddc225>

Link valid until: 29.11.2026



Created with RentalHandover SaaS · Demo Render · 31.08.2024